

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包 裝 作 業 規 范)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(规范编号)	Q9113SPP-941									PAGE	1/4	REV.	E
APPLICABLE CUSTOMER (适用客户)	ALL	APPLICABLE PRODUCT (适用产品)	9113-D14CxxD(P)P(N)RA 9113-D14CxxxP2RA							PACKAGING CATEGORY (包装方式)	TRAY PLATE PACKING		

REVISION HISTORY (修 訂 履 歷)

REV.	ECN NO	PAGE (頁 次)								
		1	2	3	4					
A		NEW (新版.)								
B		ADD P/N (新增料號)								
C		Modify package quantity (修改包裝數量)								
D		Modify package P/N (修改包材料號)								
E		Add P/N (增加料號)								

DIVISION (事業單位)	Product Development (產品開發課)	APPROVED (核 准)		CHECKED (審 核)	DE		PREPARED (制 表)	GYJ 10/30'25
					PE			

歐品電子(昆山)有限公司

OUPHIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)


SPEC.NO.(規範編號) Q9113SPP-941

CONFIDENTIAL TOP SECRET
PAGE 2/4 REV. E

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)

Laying Product Diagram: (產品擺放圖示)



(Drawing 1-1)
(圖1-1)

(Drawing 1-2)
(圖1-2)

- 一.PET Plate Packing Mode:
(PET盤包裝方式)
- (1).CT-0.5 Box: PET-9113-015 XX PCS.
(CT-0.5 規格的紙箱放盤 PET-9113-015 XX PCS)
 - (2).Put product in each trough fully as shown in diagram.
(產品在盤子中擺放方式如圖所示)
 - (3).After filling each trough with product fully,stack the xx PET plates,cover it with transparent upper cover PET-9113-016 1PCS on the top.
(每盤放滿產品後,加蓋透明上蓋 PET-9113-016 1PCS)
 - (4)The label of minimum supplies label (the design of the supplies label is such as Fig. 1-2) on each cover.
在每個蓋子的上面分別貼批次標籤(樣式如圖1-2)。
 - (5).Stack the XX PET plates filled with product, put them in the paper box in which has been put waterproof bag.
(將放滿產品的XX個PET盤疊起,裝入防水袋放入紙箱內)

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(規範編號) Q9113SPP-941

PAGE




3/4

REV.

E

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



一. Outer Box Packing Mode:

(外箱包裝方式)

- (1). Paper box 0.5 standard 1 PCS, as shown in drawing Two.
(紙箱 0.5 規格 1 PCS, 如(圖二)所示)
- (2). Put two Air column bag in the upper and lower of the paper box, 4PCS in all, as shown in drawing One.
(每箱上下各放二塊气柱袋, 共 4PCS, 如(圖一)所示)
- (3). Put 1 PCS waterproof in the paper box, as shown in drawing Two.
(紙箱內側放入防水袋 1 PCS, 如(圖二)所示)
- (4). Piled the XX packing plates packed up in the waterproof.
(將放滿產品的 XX 個 PET 盤疊起, 裝入防水袋內)
- (5). Seal the waterproof bag, then put the Air column bag 2PCS on the bag.
if box can not be full, filled with ploy.
(Put 1 PCS Air column bag at the right and left side in the paper box if it is necessary.)

封上防水袋後, 放上二塊气柱袋, 未填滿處用气柱袋填滿。
(必要時, 在紙箱的左右兩側各放一塊气柱袋)

- (6). Seal the surface of the outer box, as shown in drawing Three.
(將外箱上層封口, 如(圖三)所示)

The form on the right and flank side of the box must be filled correctly and clearly, take actual testing weight as the standard of each box gross weight.

外箱之正麥和側麥所要填寫之項目要填寫正確, 清晰, 每箱之毛重應以實測重量為準。

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(規範編號) Q9113SPP-941

PAGE: 4/4 REV. E

PACKING MATERIAL (包裝材料)			PRODUCT P/N	CT NO.	PACKING N.W.	PACKING QUANTITY (包裝數量)			WEIGHT (重量) kg		
MATERIAL NAME (材料名稱)	PART NO. (料號)	Q'TY	(產品料號)	(紙箱規格)	(包材重量)	PCS/TRAY	TRAY/BOX	PCS/BOX	N.W./PCS	N.W./BOX	G.W./BOX
PAPER BOXES (紙箱)	CT-0.5	1	9113-D14CxxxPRA	CT-0.5	3.21	40	7	280	0.017900	5.01	8.23
Packing Box (包裝盒)	PET-9113-015	7		CT-0.5	3.21	40	7	280	0.015500	4.34	7.55
Packing Box Cover (包裝盒蓋子)	PET-9113-016	7		CT-0.5	3.21	40	7	280	0.017000	4.76	7.97
WATERPROOF BAG (防水袋)	PE 100*70	1	9113-D14CxxDNRA	CT-0.5	3.21	40	7	280	0.017000	4.76	7.97
Air column bag (气柱袋)	-----	6									
DRYING AGENT (干燥劑)	-----	3									

1.NOTE:

(注意)

When the finished products have been made,take the actual weight as the standard of gross weight in each box.

(成品出貨時,每箱之毛重應以實測重量為準)

When the finished products have been made,stick the proper designation list on the box according to product demand

(成品出貨時,依據出貨要求貼上相對應的標籤單)